Survey No. B-4384

Magi No.

DOE __yes __no

Maryland Historical Trust State Historic Sites Inventory Form MARYLAND INVENTORY OF HISTORIC PROPERTIES

1.	Nam	e (indicate pre	ferred name)			
histor	ic	205 West	Saratoga Stree	et		
	r common	Saratoga	Beauty Supply	and Hosiery		3-
	Loca	ition				
street	& number	205 W. Sa	aratoga Street			not for publication
city, t		Baltimore	vicinity of	congressional d	istrict	Seventh
state		Maryland	county	Balt	imore	1
3.	Clas	sification				
<u>XX</u> t	gory district puilding(s) structure site object	Ownership public X private both Public Acquisition in process being considered not_applicable	Status X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	entertainn governme	al al nent	museum park private residence religious scientific transportation other:
4.	Own	er of Proper	ty (give names	and mailing add	iresses	of <u>all</u> owners)
name			g & Ae OK Pean			
street	& number	211a N. (Charles	teleph	one no.	:
city, t	own	Baltimore		e and zip code	MD 2:	1218
5.	Loca	tion of Lega	al Descript	ion		
court	nouse, regis	stry of deeds,Batcltimore	e City Courtho	use		1iSEB2011
street	& number	100 N. Ca	alvert Street,	Room 610		folio227
city, t	own	Baltimore	e		state	MD
6.	Rep	esentation	in Existing	Historical	Surve	ys
title						
date				federal _	state	county loca
٥٥٩	sitory for su	rvey records				
city, t	own				state	

Condition excellent	deteriorated	Check one unaltered	Check one	site	
good fair	ruins unexposed	altered	moved	date of move	

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Resource Count: 1

This circa 1875 shed-roofed commercial building faces north on W. Saratoga Street and abuts two partywall buildings. The two-bay, three-story building is part of a brick commercial block. This section, defined by seams in the brick work and changes in the fenestration, has a street frontage of 15'6 and a depth of 100'. The brick is painted white.

The first story has been altered, but sections of the original facade have been retained. To the east is a six-panel metal door with the original transom. Most of the door surround is historically intact, including the recessed field pilaster to the west and the overhanging wood cornice with dentil row. The end bracket that supports the cornice has dentil blocks at the top and grooved designs on the arm. The period cornice runs across the facade. The middle and west bays have been remodelled circa 1940 into an angled, recessed entrance flanked by large plate display windows. A folding security gate and an awning runs across the altered section.

The second story contains a central tripartite window. Narrow 1/1 sash sidelights with transoms flank a double-width central plate with transom. The window is set in wood surrounds. The lintel has a profile of fillet, ogee, bead, back band and fillets. The extended lintel has jig-sawn corner locks underneath the ends.

The third story has two 1/1 sash windows with wood sills and

brick splayed jack arches.

The wood cornice is very elaborate. It has molding with a fillet, ogee, fillet, and back band profile projecting over a row of scrolled brackets with fine details. A row of raised molding and two rows of corbelled jig-sawn and drilled leaf molding run below. A brick band terminates the bottom of the cornice. Large brackets bisect the cornice into two bays. The bold, scrolled brackets have applied rosettes on the projecting arms.

The interior of the first story is finished with wallboard,

peg board and an acoustical tile ceiling.

1400 - 1500 - 1600 - 1700	Areas of Significance—Constoric archeology-prehistoric archeology-historic agriculture architecture architect	Check and justify below	landscape architecture law literature military music philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	dates	Builder/Architect	unknown	
check:	Applicable Criteria:A and/or Applicable Exception:A	0 000 000 000	_EFG	para II
020	Level of Significance: _	nationalstate	<u>X</u> local	
Prepare	both a summary paragraph	of giomificana.		

Prepare both a summary paragraph of significance and a general statement of history and support.

This three-bay, three-story building is a good example of speculative commercial block construction along Saratoga Street during the third quarter of the nineteenth century. It is partnered with a matching mate, but the two units are separated by a brick seam indicating separate stages of construction, and have separate entrances and separate alterations to the buildings. The building's style and massing are representative of the late nineteenth-century rowhouses and partywall structures on the block. A few elements of Victorian fashion are still visible. The first story has been altered, but the nineteenth-century stringcourse-cornice remains in place. The first-story cornice was a common feature to commercial buildings in the nineteenth century and often served to demarcate the commercial from the residential zones. The cornice is supported at one end by a fine Italianate scrolled bracket, coupled with the dentil course below the cornice the

The presence of a mixed residential-commercial buildings indicates the mixed character of this Baltimore neighborhood in the nineteenth century. Architectural historian Richard Longstreth writes that "Shop-houses prevailed in emerging commercial centers of cities and towns alike through the early decades of the 19th century. Examples can still be seen in areas that have not experienced radical change, even though the shopfronts themselves have almost always been altered. . . the upper section retaining a domestic character."

This building, however, shows a new experimental aesthetic and planning device at work. Longstreth continues, "the gradual abandonment of the shop-house as the dominant form of commercial architecture was due to the everincreasing demands for trade and professional services along with a corresponding increase in land values, all of which fostered the design of buildings used entirely for commercial purposes." In

¹ Longstreth, Buildings of Main Street, p. 24.

² Longstreth, The Buildings of Main Street, pp. 24,29.

9. Major Bibliographical References

Survey No. B-4384

Richard Longstreth, The Buildings of Main Street (Washington: Preservation Press, 1987).

10. G	eographica	ii Data			
Acreage of n Quadrangle UTM Referen		 1 85	rences	Quadrang	jle scale
Zone E	asting Northin	ng	B Zone	Easting	Northing
C			D		
Verbal bou	ndary description and	justification			
	ndary description and tes and counties for p		rlapping state or c	county boundaries	s
List all stat			rlapping state or c	county boundaries	code
List all sta t		roperties over	8	county boundaries	
List all stat state state		roperties over code code	county	county boundaries	code
List all statestate	tes and counties for pr	code code	county		code
List all stat state state	orm Prepar Diane Shaw, Ar	code code code code code	county county al Historian	n	code
List all statestate state 11. F	orm Prepar Diane Shaw, Ar	code code code code code code coditectur	county county fal Historian	n	code code r 22, 1991

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

MARYLAND HISTORICAL TRUST DHCP/DHCD 100 COMMUNITY PLACE CROWNSVILLE, MD 21032-2023 301-514-7600 B-4384 205 West Saratoga Street Baltimore, MD Section 8 Signficance 8.1

this case, the commercial solution was to retain the basic shophouse form but create a commercial second-story reading. tripartite window in the second story, complete with its row of transoms, millwork lintel and corner brackets, is an early Victorian experiment in commercial architecture. The large expanse of framed plate glass and row of transoms invoked the mineteenthcentury street-level shopfront and could be used as display windows for the second-story merchant's wares. While the overall shell of the building retains the previous nineteenth-century shop-house form, the tripartite window shows an attempt to make a commercial statement from a residential building type. Before there was a clear definition of a commercial building type there was this early, experimental form. The presence of two entrances indicates that the building was constructed to hold more than one tenant, another sign that the old shop-house idea had passed. The third story, however, could have still been used as dwelling quarters.

Architecturally, this building reveals Italianate details. The third story's back band and fillet lintels and the cornice (which it shares with its row neighbor) are typical of the period. The cornice's modestly overhanging eaves are supported by small modillion brackets and bay-defining scrolled brackets, a common

way of decoratively capping the top of a building.

The twentieth-century alterations to the facade include the recessed angled vestibule. The inset entrance provided additional show cases along the interior walls and thus was a popular commercial design tactic during the World War Two period.

COMPREHENSIVE PLAN DATA

HISTORIC CONTEXT:

Geographic Organization: Piedmont

Chronological/Developmental Period:


Historic Period Themes: Architecture Economics

Resource Type: Building

Historic Environment: Urban

Historic Function and Use:

Known Design Source: None



NOTICE

THIS IS A REAL PROPERTY PLAT AS PROVIDED FOR UNDER ARTICLE 76(d) OF THE CITY CHARTER IT IS COMPILED FROM TITLE AND OTHER SOURCES AND IS NOT AN AUTHENTIC SURVEY.

DEPARTMENT OF PUBLIC WORKS

PROPERTY LOCATION DIVISION


ward 4 SECTION 10 BLOCK 597

SCALE 1'-50' DATE NOV.1966

TTERED BY PLW

ECKED BY

B-4384 Saratoga Beauty Supply & Hosiery 205 W. Saratoga Street Block 0597, Lot 020 Baltimore City Baltimore East Quad





8-4384 205 W. Saratoga St. Baltimore mo Diane Wasch 8/91 maryland 540 Facade, north elevation